

Yancey Fuel Solutions Tank Audit - Day Tank

PM Checklist

● 0 ● 0 ● 11 ● 5

Inspection Number	[REDACTED]	Customer No	[REDACTED]
Make	CATERPILLAR	Customer Name	[REDACTED]
Serial Number	[REDACTED]	Equipment Family	ENGINE - GENERATOR SET
Model	3512	Asset ID	Genset B
Customer Email	[REDACTED]	SMU	576 Hours
Completed On	10/13/2021 5:38:52 PM	Location	[REDACTED]
Inspector	Jack Wright	Coordinates	[REDACTED]
Work Order	EA06905		
PDF Generated On	10/13/2021		
Technician			


General Info & Comments

● **General info/Comments**

NORMAL

Comments: Daytank Audit.






Fuel Tank Information

1.1 Fuel Tank Serial Number

WRITE YOUR ANSWER BELOW

Comments: [REDACTED]



1.2 List associated generator(s) or equipment supplied by tank

WRITE YOUR ANSWER BELOW

Comments: [REDACTED]



1.3 Fuel Tank Capacity

WRITE YOUR ANSWER BELOW

Comments: 60


1.4 Other Relevant Tank Info?

WRITE YOUR ANSWER BELOW

Fuel Tank Condition

2.1 Fuel Pump Operation

NORMAL



● 2.2 Tank Vents Clear?

YES (PASSED)



2.2.1 Vent Pipe Size

1.25 inches

● 2.3 Fuel Level Gauge Condition

NORMAL



● 2.4 Fuel in Secondary Containment?

NO



● 2.5 Sump Area ? NORMAL

● 2.6 Other Tank Notes or Comments WRITE YOUR ANSWER BELOW

● 2.7 Fuel Level at Time of Audit 96 - 100%

Fuel Condition

● 3.1 Tank Camera Scope Analysis Performed? Comment on Findings in Tank YES



● 3.2 Fuel Inhibitor added? YES

3.2.1 Inhibitor quantity 8 ounces

● 3.3 Biocide Required? NO

3.3.1 Biocided added? 0 ounces

● 3.4 Overall Fuel Condition Notes & Comments 1 - NEW